


Renew/Update Gateway Software License

Introduction:


Gateway (Drone / Truck) software require Licenses to run. Users need to provide Gateway ID to the INOVA Personnel to obtain / renew License.

Steps to do:


1. Run the Gateway QC software as shown below:




2. The following screen will be displayed:




3. Turn on the “connection” to confirm Gateway is connected (See arrow)




4. Any discrepancies / Fault will be seen as RED as shown in below picture (see RED arrow): **In this picture we can see Firmware & License has been expired.** So, both the firmware & license need to be updated. The firmware version is decided by the Software version installed. When software patch is released then we should make sure that gate way firmware is also updated. In this document we will see how the license is updated.




5. For upgrading the license click on the setting (RED arrow)




6. Click on Manage HTG / HDG (see RED arrow)




7. Select update license System ID:




8. Go to the location where the license received from INOVA has been stored. Select / open the license file as shown below (Please don't try open / close the license file received from INOVA as it can corrupt the license file)




9. Wait till the license is updated.




10. Click OK & Close the window.



11. Reset the Gateway by resetting the ON /OFF switch (See RED arrow).



12. After Reset check the license status. It should have been updated.



13. End.